

Respector the National Register

THE PLAC PRESERVATION CERTIFICATION

APPLICATION - PART 1

(Pursuant to the Tax Reform Act of 1976)

Professions Associant should rest the instructions coloidly before completing application. No East research 2: 94.455). Use typosities or professing in dark risk to complete the application I side or a separate plain sheet of paper clearly indicating the owner's name and mailing address. I ale State Historic Proservation Officer at any time during the year, and may be sent suparately in	orm: If additional space is needed to complete Part 1: use the reverse Part 1 of this application may be completed and sent to the appropri-
PART 1 EVALUATION OF SIGNIFICANCE	
1. NAME OF PROPERTY:	
Address of property Street 816 Park Avenue	
cm Baltimore County Sta	ne Maryland zip Code 21202
Name of historic district in which properly is located Baltimore City Historic	
2 DESCRIPTION OF PHYSICAL APPEARANCE. (see instructions for map and photograph requirements—use reverse side if necessary)	
SEE ATTACHED SHEETS	182
3 STATEMENT OF SIGNIFICANCE:	¥
(use levuise side if heressely)	
SEE ATTACHED SHEETS	= x
Date of construction (if known) C. 1845 M Original site 17 Move 4. NAME AND MAILING ADDRESS OF OWNER:	Date of afferations (if known) mid 20th cent.
ne Sommers and Sommers, c/o Miltom Sommers	
Sweet 824 Park Avenue	
CityBaltimore	
Telephone Number (during day) Area Code _(301) 728-1400	
I hereby atlest that the information I have provided is to the best of my knowledge correct	and that I am owner of the property described above
Prepared by: Barbara Hoff, Dalsemer, Catzen and 7	issociates, Inc. Date 1 21202
For office use only	• •
The structure described above is included within the boundaries of the National Register historic the district.	district and a contributes of does not contribute to the character of
The structure Happears, 1 does not appear to meet National Register Criteria for Evaluation (36 Register in accord with the Department of the Interior procedures (36 CFR 60).	CFR 60.5) and ∩ will likely □ will not be nominated to the National.
The structure is located in a district which: I appears. I does not appear to meet National Register nated to the National Register in accord with Department of the interior procedures to CFH out and district.	nd. 3 appears: I dives not appear to contribute to the character of said
StyriatureStyriature Preservation Officer	Date 3-11-82
This property has been evaluated according to the criteria and procedures set forth by the Depart section 167 of the Internal Rovernae Code of 1954. This hereby certified a historic structure. I have not contribute to the character of the historic district and does not ment certification as	** n = 0.000
5.0" Nuie	0.40

	2
306	6

ame/address	of Property:	816 Park Av	enue, Baltimo	ore, Maryland 21	1202	** x -x *x	****
ara, dress	of Owner: Sc	ommers & Somme	rs , 824 Park	Avenue, Baltimo	ore, Maryland	1 - 8150	2
					Telephone:	(301)	728-1400
repared by:	Barbara Ho	ff, Dalsemer,	Catzen and A	ssociates, Inc.			
		re, Maryland	674		Telephone:	(301)	837-3691

ESTRIPTION OF PHYSICAL APPEARANCE

816 Park Avenue exemplifies the elaborate simple, elegant rowhouses found in the Mount ernon Historic District. Buildings such as it blend with one another to create the ignificant architectural environment of the district. The building is an Italianate, three tory, three bay, masonry double house with a facade of running bond brick and a shed roof.

It has a marble high basement with a belt course beneath the first floor windows. The as ment has two bays of one over one double hung windows with delicate wrought iron screens. here is an iron stairway that goes from the sidewalk below the front steps and into the orth basement bay. The front steps were probably originally marble and have been replaced ith brick and a simple iron railing.

The first level comprises two windows and the entrance. The windows are eight over ight wood sash double hung windows with a wood panel below indicating that the windows were not uch larger and have been replaced with shorter windows. The windows have white unstorm windows over them, flat arches, and marble sills.

The entrance in the north bay has been modified. It comprises a metal swinging door ith a simple wood frame around it, around that is wood paneling and a large projecting cornice ith brackets; the cornice has some decorative molding.

The second floor comprises three one over one double hung wood frame sash windows with arble sills, flat arches, and white aluminum storm windows. The third story windows have destical details. All these windows, though, become shorter at each upper story. Above he third floor lintels is a brick fascia composed of brick which does not match that of the compart of the facade. The cornice is simple and large with decoratively sawn modillions, and dentils. In the attic level are three vents covered with simple iron grates.

Both the north and south walls of the structure are attached to adjacent buildings. The est wall of the main building has a two bay wide, two story shed roofed back building attached the northern and central bay. The southern bay has six over six double hung wood windows at ach story, with flat metal strip lintels, rowlock brick sills, and aluminum storm windows. An con fire escape extends down the bay.

The back building is constructed of partially stuccoed and painted common bond brick. The buth wall is plain brick, and what is visible of the north wall is also plain brick. The irst floor of the west wall has an unoriginal paneled wood door in the northern bay. The eccod and third stories contain one over one wood sash windows with aluminum storm windows, etal strip lintels, and stone sills. An iron fire escape extends down the wall. The coping file roof line indicates that the roof has been altered.

Fabind these structures there is a two story high, three bay wide, four bay long carriage by built of common bond brick. It has a shed roof. On the first floor, east wall, there is a doorway and three one by one casement windows with wood sills and a flat arch.

HISTORIC PRESERVATION CERTIFICATION APPLICATION - FART I - continued.	Page 3
N. se/address of Property: _ 816 Park Avenue, Baltimore, Maryland 21202	B-3790
Control of the Contro	

DESCRIPTION OF PHYSICAL APPEARANCE

bove are six over six double hung wood windows with wood sills and flat arches. There is corbelled cornice with brick modillions at the caves. The north and south walls consist of plain brick. The painted west wall comprises—two large bays and two stories. The irst story consists of two plain wood doors on either side of a large double plain metal cor. There is an "I" beam lintel above. In the north bay of the second story there is a ix over one double hung wood window with a wood sash and a flat arch. The south bay contains to be tongue and groove wood doors with a wood sill and flat arch. Above these openings there is a corbelled cornice.

The interior still retains its original floor plan of rooms organized in a line parallel o a circulation axis, and the rooms have been converted into apartments with a variety of urface finishes applied during recent years.

The front door of the house originally had a large round arched doorway with an architrave authority, now filled in and reduced in size. The doorway from the vestibule to the hallway has a Colonial Revival (not original) pedimented door with fluted pilasters, a broken pediment with modillions, and a central finial. The stairs retain their original open string, bracketed taircase with a heavily molded newel post and turned balusters.

The apartments are very simple with plain surrounds on openings, no baseboard or mountaings, some original wood floors, and wood paneled doors.

The conversion of this structure into an apartment house is typical of the area which how consists mainly of professional offices and apartments. In general, the building still retains its original character in its materials, scale, plan, proportion, and details. As a result, the building augments the special environment of the Mount Vernon Historic District.

me/address of Property: 816 Park Avenue, Baltimore, MD 21202

me/address of Owner: Somers and Somers, 824 Park Avenue

Baltimore, Maryland 21202

Telephone: (301) 728-1400

epared by: Barbara Hoff, Dalsemer, Catzen and Associates, Inc.

14 Light Street, Baltimore, MD 21202 Telephone: (301) 837-3691


ATEMENT OF SIGNIFICANCE


The significance of 816 Fark Avenue lies in its architectural contribution to the environment of the Mount Varnon Historic District.


The Mount Vernon Historic District is both a Baltimore City District and, in part, a National Register Historic Landmark District. Mount Vernon was the first Historic District in Baltimore City, designated in 1964 and expanded five times to the current boundaries, which have been certified by the Department of the Interior for purposes of the Historic Preservation Tax Incentives. The ordinance creating the Mount Vernon Historic District also established the Baltimore City Commission for Historic and Architectural Preservation to oversee all changes within the Distict and to recommend other areas and buildings in the City for historic designation. The Historic District and the Commission were outgrowths of the Mount Vernon Urban Renewal Plan, one of the City's earliest efforts to incorporate preservation and renovation of existing structures with new development. The current Historic District now encompasses two Urban Renewal Areas: Mount Vernon and Midtown-Belvedere.


The Hount Vernon Historic District grew from the early 19th century through the early 20th century and retains structures--residential, commercial, and religious -- from that time. The area was Baltimore's most fashionable neighborhood and as such includes some of the finest architecture in the City, built for wealthy residents, congregations, and institutions, and designed by architects of local and rational renown. The greater portion of the district was once the estate of John Eiger Howard, revolutionary war patriot and statesman. His mansion, Belvidere, was located at what is now the 1000 block of North Calvert Street. The centerpiece of the district is the Washington Monument and Mount Vernon Place. The monument is the first formal monument erected to conmemorate George Washington and is one of the finest examples of monumental architecture in the country. It was erected from 1815 to 1829 and designed by Robert Mills, one of the first American born and trained architects in the country. The development of the squares known as Mount Vernon Place and Washington Place, dates from the 1830's, when the land was subdivided by Howard's heirs, who then built some of the first houses. Prior to the construction of the monument and the development of the squares, brick working class houses were built on Tyson Street, Read Street and North Howard Street, the earliest dating from 1810. These buildings still exist, some are residences and others have been converted to antique shops. The houses on Hamilton Street date from 1820 and were designed by Robert Cary Long Sr. the architect of the Peale Museum and Davidge Hall.

The area which is now the Historic District continued to develop. Baltimore's prominent and wealthy residents moved north to the rural area because the land ar ind the harbor was rapidly becoming industrialized and because the City was f. Jed with immigrants, who flocked to Baltimore to work in the newly established industries. Construction continued to take place in the 1880's and 1890's after the I ward estate had been sold. By the early 20th century, Mount Royal Avenue and jurts of Howard Street had been developed, completing the construction in the district.









B-3790 816 Park Avenue Block 0509, Lot 014 Baltimore City Baltimore East Quad.

